

Detroit District P.O. Box 1027 Detroit, MI 48231-1027 (313) 226-6797 FAX - (313) 226-3519

Notice to Navigation Interests

Notice No. L04-79	Date: 9 DECEMBER 2004

Waterway: LAKE ERIE Location: MICHIGAN

CELRE-OT-T


CONDITION OF FEDERAL NAVIGATION CHANNEL MONROE HARBOR


- 1. Condition surveys performed within the Federal navigation channel at Monroe Harbor, Michigan during July October 2004, indicate shoaling as shown on the back of this sheet.
- 2. Mariners are urged to use extreme caution in the area.
- 3. All inquiries should be addressed to CELRE-OT-T and should refer to Notice to Navigation Interests No. L04-79. Internet address: http://www.lre.usace.army.mil Go to: Detroit Home Page, Who We Are, Operations Home Page.

DONALD P. LAUZON Lieutenant Colonel, U.S. Army District Engineer

Notice to the Postmaster:

It is requested that the above notice be conspicuously and continuously posted until December 31, 2004.





The information depicted on this map represents the results of surveys made on the date indicated and can only be considered as indicating the general conditions existing at that time.

Omonroe.bmp

Surveys taken: JULY - OCTOBER 2004

Shoals indicate least available depth below LWD

Elevations and project depths are referred to IGLD, 1985 when Lake Erie is at elevation 569.2 ft. above Mean Sea Level.

MONROE HARBOR, MICHIGAN

CONDITION OF CHANNEL

ISSUED: 9 DECEMBER 2004

U.S. Army Engineer District, Detroit